SHEARWATER MAINTENANCE ISSUES FOR FEBRUARY 2010

DATE	ADDRESS	CALLER	MAINTENANCE ISSUE	ASSIGNED TO	OUTCOME
2/2/	4A	Barbara Britt	3 downspout & run off tubes behind condo do not stay attached & are too short	John	Completed
2/10/10	16B2	Harold Shaw	Please have snow removed from around the HVAC units on the flat roofs	John	Completed
2/16/10	14B3	Heidi Segal	Please have snow removed from around the HVAC units on the flat roofs	John	Completed
2/21/10	15A	Patti Connell	Raccoons on deck	John	John placed trap caught a raccoon
2/25/10	7A3	Darlene Marks	Water leaking from exterior and damaging the dinning room floor	Cunningham	Water coming in from damaged exterior siding. BOD chose Cunningham to repair. Repair completed