October 2011

DATE	ADDRESS	CALLER	MAINTENANCE ISSUE	ASSIGNED TO	OUTCOME
10/3	7 B2	Internal	lights on 2nd floor/ hallway/security path	John	completed
10/3	11 B3	Nickels	Roof Leak	Cunningham	completed, the leak is fixed. Flashing problem
10/10	5B1	Smith	deck leaking	Cunningham	Performed one fix, but did not completely stop problem. Scheduled to do another fix on deck above
10/14	8A	Avery	light on east side of building 8 is not working	John	completed
10/21	3&4	Petterson	lights not coming on at right time	John	completed
10/24	9A	Trefrey	street light out	John	completed
10/25	1B3	Petterson	lower deck railing needs replacement	Cunningham	will do when deck is replaced
10/25	13A2	Watts	Boards on new deck split	Cunningham	completed
31-Oct	9A	Trefrey	window leaking	Cunningham	completed