

SHEARWATER MAINTENANCE ISSUES FOR DECEM

DATE	ADDRESS	CALLER	MAINTENANCE ISSUE	ASSIGNED TO
12/6	Bldg 6		sensor light out on the stairs	John
12/6	Bldg 3		light out on side of building	John
12/14	Bldg 11		two lights out in front of building	John
12/25	12A3	Fisher	wet ceiling by the skylights	Cunningham
12/29		Higgins	parking lot lights not on at 6 am very dark	John
12/30	14B3	Segal	gutter from roof above hanging	Cunningham

BER 2010

OUTCOME
completed
completed
completed
Main cause was the sky light leaking, because it was left open a little. (unit owner responsibility) Cunningham did find deteriorated caulking on rain collars & flue pipes. Caulking was removed and resealed
John adjusted timer
repaired